


Humidity and Temperature Sensor

Model: HTS 02



Specifications

Measuring Range	35 to 85 % RH 0 to 50°C
Accuracy @ 23°C	± 3 % RH / ± 0.5 K Pt100
Operating Range	0 to 100 % RH / 0 to 85 °C
Output	0 - 3 V DC (0 ~ 100%RH) / PT 100
1st measurement value after Measurement interval	2.3 s 0.7 s
Supply Voltage	5 VDC / approx. 3 mA / > 10 kOhms
Mounting	Wall Mounting

SANSEL INSTRUMENTS AND CONTROLS SANSEL CALIBRATION LABORATORIES

NABL Accredited Calibration Lab (Thermal, Mechanical, Electro-Technical Parameters)
 1 / 46 , Ganga Nagar, MMDA Colony , Maduravoyal , Chennai - 600 095. INDIA
 ☎ +91 44 2378 3951 , +91 44 2378 3941 📞 +91 7299972091 ✉ enquiry@ sanel.net